

# TITAN MACHINERY

## USED VEHICLE CONDITION REPORT

ASSET #: 12383

STORE NAME & NUMBER: Albuquerque 355

TITAN EMPLOYEE NAME: Dominick Gonzales

YR.	MAKE	MODEL	BODY	SERIAL NUMBER	LIC PLATE NO/STATE/YR
06	Ford	F-650	Truck	3FRWFG5F77V460009	MZH636/NM/18
EXTERIOR COLOR		INTERIOR		ENGINE	TRANSMISSION
White		<input type="checkbox"/> CLOTH <input checked="" type="checkbox"/> LEATHER <input type="checkbox"/> VINYL		<input type="checkbox"/> 8CYL <input checked="" type="checkbox"/> 6CYL <input type="checkbox"/> 4CYL <input checked="" type="checkbox"/> DIESEL	<input checked="" type="checkbox"/> AUTOMATIC <input type="checkbox"/> AUTOMATIC O.D. <input type="checkbox"/> MANUAL <input type="checkbox"/> SPEED
AIR CONDITIONER		RADIO		EQUIPMENT	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> AM <input checked="" type="checkbox"/> CD PLAYER <input checked="" type="checkbox"/> AM/FM <input checked="" type="checkbox"/> CASSETTE		<input checked="" type="checkbox"/> P. STEERING <input type="checkbox"/> ANTI-LOCK BRAKES <input checked="" type="checkbox"/> P. WINDOWS <input checked="" type="checkbox"/> P. LOCKS <input checked="" type="checkbox"/> CRUISE <input type="checkbox"/> SUN-ROOF <input type="checkbox"/> P. SEAT <input checked="" type="checkbox"/> TILT	
PRESENT MILEAGE <u>138,345</u>				ESTIMATE THE NUMBER OF MILES THAT THIS VEHICLE WILL BE DRIVEN IN THE NEXT 30 DAYS <u>30</u>	
<input checked="" type="checkbox"/> ACTUAL <input type="checkbox"/> OVER 100,000 <input type="checkbox"/> UNKNOWN					

**BODY CONDITION:** DESCRIBE DENTS, CREASES, RUST, CONDITION OF PAINT.

FRONT/HOOD: minor scratches & chips

LEFT SIDE: Scratches, chips, & scuffs

REAR: Scratches, chips, & surface rust on rear bumper

RIGHT SIDE: Scratches, chips, & scuffs

ROOF: Good

BUMPERS/WHEEL COVERS: Rear bumper starting to rust

MLDGS/GRILLE: Good / Grille starting to peel

**WINDSHIELD:**  OK  CRACKED  CHIPPED  SCRATCHED - WHERE? \_\_\_\_\_

OTHER GLASS Good

**TIRES:** (GOOD, FAIR, POOR) L. FRT Good R. FRT Good L. RR Good R. RR Good SPARE Good

**INTERIOR CONDITION:** WORN, TORN, STAINED, SOILED, BURN HOLES

FRONT SEAT: Good / Stained REAR SEAT: N/A

HEADLINER: Stained CARPETS: Stained

TRUNK/CARGO AREA: Scratched / dented OTHER: \_\_\_\_\_

**MECHANICAL CONDITION:**

ENGINE: Good TRANSMISSION: Good

DRIVETRAIN: Good BRAKES: Good

FRONT END: Good EXHAUST SYSTEM: Good

AIR CONDITIONER: Good OTHER: \_\_\_\_\_

ESTIMATE OF REPAIR COSTS	BODY \$	GLASS \$	TIRES \$	INTERIOR \$	MECHANICAL \$	TOTAL \$
DRIVER'S SIGNATURE			DATE	DEALER'S SIGNATURE		